



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES


MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

0001

Inspection Report Minerals Regulatory Program January 6, 2010

Reviewed: 

Mine Name: Walker Iron Mine Placer	Permit Number: S/021/0038
Operator Name: Iron County	Inspection Date: May 20, 2009
Inspector(s): T Munson	Time: 9AM
Other Participants: none	Mine Status: Ins

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$18,400.00

Permit Fees: Current


Purpose of Inspection: Site inspection. The last site inspection was 04/25/08.

Inspection Summary: Site was actively being mined to crush various sizes of rock. No problems were found at the site.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The site be subject to regular inspections.

Inspector's Signature 

TM:vs

cc: Fiddlers Canyon Development Ltd., 2045 N Main, Cedar City, Ut 84770
O:\M021-Iron\S0210038-WalkerIron\inspections\Insp-05202009.doc




0001




Crushing equipment



Pad area



Active disturbed face



Pad area